




7. Tape other end of cardboard as shown





## Before step 10




## 11. Tape cardboard at edges.











Top view before connecting wires



14. Connect both black wires to each other.

Make sure the metal parts touch. Secure with tape or solder.



14. Connect both red wires to the potentiometer at the positions shown.Tape or solder the wire on the left side.Use the middle wire to turn the motor on and off.